ERRATA LIST FOR KBK9G20

1 USB HOST PORTS 2/3 SUSCEPTIBLE TO EMI

Affected versions: 0.90 - 0.95 Impact:

During long USB transfers, the port may be reset by the processor. This does not affect low-rate bulk devices like keyboards and mice, but may degrade functionality on more active links such as USB/Ethernet adapters. The issue has not yet been identified on port 1.

Workaround: None